



Entrance Channel 2011 Bathymetry & Athena Washprobes

Entrance Channel Sub-Sections 2011 Condition Survey		40 - 44	56 - 58
Athena 2013 Washprobes	Bathymetry (MLLW)	44 - 46	58 - 60
Refusal within Dredge Prism	25.2 - 30	46 - 48	60 - 65
Below -56 MLLW	30 - 34	48 - 52	65 - 70
No Refusal Encountered	34 - 38	52 - 54	70 - 75
Poss Rock Encountered	38 - 40	54 - 56	
Video			

OB = Ocean Bottom
TOR = Top of Refusal

PLATE 4: CHARLESTON HARBOR ENTRANCE CHANNEL WASHPROBE LOCATION MAP & REFUSAL DEPTH

EXPLORATION BY ATHENA TECHNOLOGIES

